

# **EXHIBIT I**

## Silverado

17-0089255

## Outages

|                          |   |                      |   |
|--------------------------|---|----------------------|---|
| Circuit                  | 043291104, PUEBLO-1104  | District             | Silverado   |
| Type                     | Unplanned   | Customer Minutes     | <a href="#">Sus</a> 197680 0 197680 <a href="#">CAIDI</a> 19768 <a href="#">Mom</a> <a href="#">Adj</a> <a href="#">Sus</a> |
| Customers                | <a href="#">CESO</a> 10 <a href="#">CEMO</a> 0 <a href="#">ADJ</a> 10 <a href="#">Initial</a> 10 <a href="#">CESO</a> | Weather              | Clear;32-90 F   |
| Active                   | NO  | Fault Type           | Line to Ground  |
| Interval                 | Sustained   | Action Required      | No  |
| EquipID                  | SW 861209   | Construction Type    | OH  |
| Equipment Type           | Jumpers   | OIS Outage#          | 1906414   |
| Equipment Condition      | Pole-Wood, Broken   | Targets              |   |
| Crew Notified Time       |   | Supervisor Notified  |   |
| Equipment Address        | 6 SPAN LD SIDE OF FUCO 709  |                      |   |
| Fault Location           | MULTIPLE POLES  |                      |   |
| Previous Switching       | 9595 OPEN   |                      |   |
| Details                  |   |                      |   |
| Action Description       |   |                      |   |
| Cause                    | Equipment Failure/Involved, Overhead  | No Access Reason     |   |
| Distribution Wire Down   | No  | Wire Down Energized  | No  |
| Multi Damage Location    | No  | # of Operations      |   |
| Counter Read             |   | Created By           | D1LV  |
| Outage Level             | Distribution Circuit  | Last Updated By      | SMBATCH_FO  |
| Responsible Organization | Distribution  | Fault Location Info  |   |
| GPS MA Data              |   | Latitude & Longitude |   |
| FNL                      | 10/08/17 22:59  | Reviewed By          | D1LV  |
| End Date                 | 10/22/17 16:27  | Reviewed By Date     | 10/22/17 17:16  |

## Actions

| Date           | Description   | Customers Restored | Customers Out | Minutes Out | Customer Minutes |
|----------------|---|--------------------|---------------|-------------|------------------|
| 10/08/17 22:59 | SBCO 861209 OPEN  | 0                  | 10            |             | .                |
| 10/20/17 16:48 | T-MAN/BOCK OPEN SBCO 861209 ON A DEADLINE   | 0                  | .             |             | .                |
| 10/20/17 17:24 | T-MAN/BOCK RPTS CANNOT GO PAST THIS NEWLY INSTALLED SBCO 861209 DUE TO INVESTIGATION AREA | 0                  | .             |             | .                |
| 10/22/17 09:12 | CREW/TITUS WLL HOLD HIS OWN TO EOL  | 0                  | .             |             | .                |
| 10/22/17 16:27 | CREW/TITUS CLO SW 861209 PICKING UP LD  | 10                 | 0             | 19768       | 197680           |
| 10/26/17 15:17 | OQT REPLAY OUTAGE. UPDATE FNL AND PREVIOUS SWITCHING.                                     | 0                  | .             |             | .                |

## Device History

| FNL            | Outnum     | Circuit ID | Customers Affected | Interval  | Cause                                |
|----------------|------------|------------|--------------------|-----------|--------------------------------------|
| 10/08/17 22:59 | 17-0089255 | 043291104  | 10                 | Sustained | Equipment Failure/Involved, Overhead |

### Outage Data Change History (Items with bold/blue Change Date have changed since last post)

- Show Changes Since Last Post

| Change Date    | Field Changed | Old Value        | New Value        | Changed By |
|----------------|---------------|------------------|------------------|------------|
| 10/26/17 15:17 | FNL           | 10/08/2017 21:32 | 10/08/2017 22:59 | JBG8       |

|                |                    |          |           |      |
|----------------|--------------------|----------|-----------|------|
| 10/26/17 15:17 | Previous Switching | No Value | 9595 OPEN | JBG8 |
| 10/22/17 17:16 | Reviewed By        | No Value | D1LV      | D1LV |

**Outage Action Change History (Items with bold/blue Action Date have changed since last post)** - Show Changes Since Last Post

| Action Date           | Description   | Customers Restored | Changed By | Change Date      | Edit Type |
|-----------------------|---|--------------------|------------|------------------|-----------|
| 10/26/2017 15:17      | OQT REPLAY OUTAGE. UPDATE FNL AND PREVIOUS SWITCHING.                                     | 0                  | jbg8       | 10/26/2017 15:17 | UPDATED   |
| 10/26/2017 15:17      | OQT REPLAY OUTAGE. UPDATE FNL AND PREVIOUS SWITCHING.                                     | 0                  | jbg8       | 10/26/2017 15:17 |           |
| 10/22/2017 16:27      | CREW/TITUS CLO SW 861209 PICKING UP LD  | 10                 | jbg8       | 10/26/2017 15:17 | UPDATED   |
| 10/22/2017 16:27      | CREW/TITUS CLO SW 861209 PICKING UP LD  | 10                 | jbg8       | 10/26/2017 15:17 |           |
| 10/22/2017 09:12      | CREW/TITUS WLL HOLD HIS OWN TO EOL  | 0                  | jbg8       | 10/26/2017 15:17 | UPDATED   |
| 10/22/2017 09:12      | CREW/TITUS WLL HOLD HIS OWN TO EOL  | 0                  | jbg8       | 10/26/2017 15:17 |           |
| 10/20/2017 17:24      | T-MAN/BOCK RPTS CANNOT GO PAST THIS NEWLY INSTALLED SBCO 861209 DUE TO INVESTIGATION AREA | 0                  | jbg8       | 10/26/2017 15:17 | UPDATED   |
| 10/20/2017 17:24      | T-MAN/BOCK RPTS CANNOT GO PAST THIS NEWLY INSTALLED SBCO 861209 DUE TO INVESTIGATION AREA | 0                  | jbg8       | 10/26/2017 15:17 |           |
| 10/20/2017 16:48      | T-MAN/BOCK OPEN SBCO 861209 ON A DEADLINE   | 0                  | jbg8       | 10/26/2017 15:17 | UPDATED   |
| 10/20/2017 16:48      | T-MAN/BOCK OPEN SBCO 861209 ON A DEADLINE   | 0                  | jbg8       | 10/26/2017 15:17 |           |
| 10/08/2017 22:59      | SBCO 861209 OPEN  | 0                  | jbg8       | 10/26/2017 15:17 | UPDATED   |
| 10/08/2017 22:59      | SBCO 861209 OPEN  | 0                  | jbg8       | 10/26/2017 15:17 |           |
| 10/22/2017 16:27      | CREW/TITUS CLO SW 861209 PICKING UP LD  | 10                 | jbg8       | 10/26/2017 15:06 | DELETED   |
| 10/20/2017 16:48      | T-MAN/BOCK OPEN SBCO 861209 ON A DEADLINE   | 0                  | jbg8       | 10/26/2017 15:06 | DELETED   |
| 10/22/2017 09:12      | CREW/TITUS WLL HOLD HIS OWN TO EOL  | 0                  | jbg8       | 10/26/2017 15:06 | DELETED   |
| 10/08/2017 22:59      | SBCO 861209 OPEN  | 0                  | jbg8       | 10/26/2017 15:06 | DELETED   |
| 10/20/2017 17:24      | T-MAN/BOCK RPTS CANNOT GO PAST THIS NEWLY INSTALLED SBCO 861209 DUE TO INVESTIGATION AREA | 0                  | jbg8       | 10/26/2017 15:06 | DELETED   |
| 10/22/2017 16:27      | CREW/TITUS CLO SW 861209 PICKING UP LD  | 10                 | d1lv       | 10/22/2017 17:16 | DELETED   |
| 10/22/2017 09:12      | CREW/TITUS WLL HOLD HIS OWN TO EOL  | 0                  | d1lv       | 10/22/2017 09:13 | DELETED   |
| 10/20/2017 17:24      | T-MAN/BOCK RPTS CANNOT GO PAST THIS NEWLY INSTALLED SBCO 861209 DUE TO INVESTIGATION AREA | 0                  | d1lv       | 10/20/2017 17:24 | DELETED   |
| 10/20/2017 16:48      | T-MAN/BOCK OPEN SBCO 861209 ON A DEADLINE   | 0                  | d1lv       | 10/20/2017 16:49 | DELETED   |
| Outage Last Posted on |   |                    |            |                  |           |

